

| 5  | BST-1YSS      | Stainless Steel Female QC(viton)<br>Brass Female QC  |  |
|--|---------------|--|--|
| 6  | 6590          | Br/SS Trig/valve   |  |
| *  | 6590-ORING    | Trig/Valve O RING ONLY (viton)   |  |
| 7  | H142MUSBR     | Compression & Strain relief  |  |
| 8  | FW-10         | Coil Spray Hose 1/4" I.D.(or) includes #H142MUSBR  |  |
| 8  | 801-4-10      | Straight Spray Hose 1/4" I.D. includes hose barb, spring guard & clamp   |  |
| 9  | SNP-2         | Snap Clamp   |  |
| 11   | N4MEB6        | Nylon Elbow, 3/8 NPT   |  |
| 12   | AQ115         | Aquatec Motor/Pump # 5882-8F71-B584, 115 V, 70 psi   |  |
| 13   | 2G            | 2 Gallon Solution Container/w 43 mm opening (shipping can increase jug cost substantially)                         |  |
| 14   | 216P-4-2      | Brass Reduce Nipple  |  |
| 15   | 11375         | Rubber Hose Grommet  |  |
| 16   | ARD*          | Nylon Base Plate Ret. Pin(4)   |  |
| 17   | 160011E       | ON/OFF Switch  |  |
| 18   | UR33          | Urethane Hose, 33", 1/4"I.D., Pump to #19. Old # was 801-4-46  |  |
| *  | 9600K35       | Cap/Grommet(on suction hose)Old Design   |  |
| 19   | F17004LG      | Female QC with check valve, will not drip  |  |
| 20   | M22004LG      | Male QC with check valve (inc. cap & panel mount, not dip tube) (Male QC only # M22, without cap and panel mount,) |  |
| 22   | UR12.5        | 12.5", 1/4" I.D. urethane tube   |  |
| 23   | 13862-50      | Suction Hose Strainer  |  |
| 24   | 4193A-10-50SS | Strainer check valve inside brass body (#2A-#CP1336)   |  |
| 25   | BST-N1SS      | Male QC, stainless steel. (brass is #BST-N1) brass on #WACS, SS on #WAC  |  |
| 26   | M3251         | Pigtail Cord Restrainer (start 2015)   |  |
| 27   | 18110         | Power cord 20'   |  |
| Cart   | 2000-227-43   | 2 Wheel Cart for M, TC and SC Models   |  |
| Aquatec  | Pump Parts    | #UHA-115 Black Pump Head for "M", 115 volt   |  |
|  |               | #UHA-12 Black Pump Head for "TC & SC", 12 volt   |  |
|  |               | #VHA Valve Assembly - (same for 115 & 12 volt)   |  |
|  |               | #LHA Diaphragm/CAM - (same for 115 & 12 volt)  |  |
| If Aquatec pump runs but does not spray, replace #VHA & #LHA. If Aquatec pump leaks from small triangle on black pump head (#LHA), replace #LHA. Always spray fresh water after use of diluted |               |  |  |

If Aquatec pump runs but does not spray, replace #VHA & #LHA. If Aquatec pump leaks from small triangle on black pump head (#UHA), replace #UHA. Always spray fresh water after use of diluted solvents and at the end of the day.

M1 wand parts: #8004WAND

H1/8DT-SS8004 is female V-Jet Tip, SS20- is threaded 20 inch SS tube, AB110CA-is 1/8/1/4 brass connector

M2 wand parts: #WAC #WACS

| WAC<br>(carpet wand) | BST-N1SS-(male QC-brass available #BST-N1), threaded 20 inch SS tube-\$<br>CP1335-(brass body), 4193-A-10-50SS-(50 mesh strainer with 10 lb. check<br>valve), TPU8004SS-(SS T-Jet tip), CP1325-(Brass hex nut). |
|----------------------|---|
| WACS (uphols. tool)  | BST-N1-(Brass male QC), CP1336-(brass male body), 4193-A-20-50-(50 mesh strainer with 20 lb. check valve), TPU50015-(BrassT-Jet tip), CP1325-(brass hex nut)  |